NEW



#### NTRODUCING

## **Twiflex USA Rebuild Center**

Twiflex USA can refurbish your old, worn calipers for considerably less cost than the replacement of a new Twiflex caliper assembly

Twiflex USA keeps most replacement and spare items in-stock. This results in shorter turnaround time than typically associated with new units. Shorter turnarounds can make shutdown planning easier.

Twiflex USA inspects all consumable wear items to determine if replacement is necessary. Integral metal parts, such as cylinders and pistons, are inspected for scratches or signs of wear that can cause leakage or premature failure of other common wear items.

After inspection, units are refurbished to original condition. The same cycle and hold testing that is performed on new units is conducted on all refurbished units to guarantee that they are returned in like-new condition.

Unless otherwise informed during teardown and inspection, Twiflex USA will replace all known wear items and warranty these under our standard terms and conditions.

In addition to Twiflex USA repair capabilities in-house, we also offer on-site inspection and repair by trained service technicians.

#### *For more details on the rebuild program, please call 844-723-3483 or email us at twiflex.info@twiflex.com*

#### Cost Effective

Cost effective alternative to caliper replacement

#### • Fast

Often faster than acquisition of new brake assemblies

#### Comprehensive

Includes all common wearable and integral items

#### Like-New

Refurbished to original condition and warrantied as such





### TWIFLEX REBUILD LOCATIONS

Cost-effective alternative to caliper assembly replacement

#### USA

2800 Fisher Road Wichita Falls, TX 76302 - USA 940-723-3483 Toll free: 844-723-3483 twiflex.info@twiflex.com

#### UNITED KINGDOM

Ampthill Road Bedford, MK42 9RD - UK +44 (0)1234 350311 info@twiflex.com sales@twiflex.com





# Before After

*For more details on the rebuild program, please call 844-723-3483 or email us at twiflex.info@twiflex.com* 



#### www.twiflex.com

2800 Fisher Road Wichita Falls, TX 76302 - USA 940-723-3400 9 Briar Road, Twickenham Middlesex TW2 6RB – England +44 (0) 20 8894 1161